2501/205 STRUCTURAL FABRICATION TECHNOLOGY, MATERIALS AND METALLURGY II Oct/Nov. 2022

Time: 3 hours



## THE KENYA NATIONAL EXAMINATIONS COUNCIL

## DIPLOMA IN MECHANICAL ENGINEERING (PRODUCTION OPTION) MODULE II

STRUCTURAL FABRICATION TECHNOLOGY, MATERIALS AND METALLURGY II

3 hours

## INSTRUCTIONS TO CANDIDATES

You should have the following for this examination

Answer booklet:

Drawing instruments;

Scientific calculator.

This paper consists of EIGHT questions in TWO sections; A and B.

Answer FIVE questions taking at least TWO questions from each section in the answer booklet provided.

All questions carry equal marks.

Maximum marks for each part of a question are indicated.

Candidates should answer the questions in English.

This paper consists of 4 printed pages.



Candidates should check the question paper to ascertain that all the pages are printed as indicated and that no questions are missing.

D 2022 The Kenya National Examinations Council

Turn over

363

## SECTION A: STRUCTURAL FABRICATION TECHNOLOGY

Answer at least TWO questions from this section.

1.	(a)	Define each of the following terms as used in sheet metal industry:		
		(i) pattern; (ii) surface development; (iii) tab.	(3 marks)	
	(b)	With the aid of sketches, explain each of the following methods of surface development:		
		(i) parallel line; (ii) radial line.	(8 marks)	
	(c)	(i) Define the term ergonomics as used in engineering deign.		
		(ii) State four ergonomic risk factors associated with welding.	(5 marks)	
	(d)	Explain each of the following safety measures with regard to machine operations:		
		(i) interlocking machine guard; (ii) fail safe machine design:	(4 marks)	
Z	(a)	(i) Sketch a standard metallic roof frame and label four components.		
		<ul> <li>State four factors to consider when selecting the final solution in process.</li> </ul>	the design (12 marks)	
	(b)	Explain four types of datum used in marking out and measurement in fa	brication. (8 marks)	
*	(a)	(i) Explain four components of the tungsten inert gas (TIG) welding equipment.		
		<ul> <li>(ii) Identify two types of tungsten inert gas welding (IIG) electrodes application for of each.</li> </ul>	s and state the (8 marks)	
	(b)	State four factors that affect the quality of a weld. (4 marks)		
	(c)	<ul> <li>(i) With the aid of a sketch, explain the working pricinple of metal inert gas (MIG) welding.</li> </ul>		
		(ii) State two advantages of MIG welding over other welding process	sses. (8 marks)	

(a) Explain resistance welding process. (2 marks) (b) Describe two types of spot welding machines. (6 marks) (c) Differentiate between flash welding and butt welding as applied to resistance welding. (4 marks) (d) With the aid of a sketch, describe seam welding process. (8 marks) SECTION B: MATERIALS AND METALLURGY Answer at least TWO questions from this section. 5. Explain three precautions to be observed when undertaking a hardness test for (a) materials. (6 marks) (b) (i) State five advantages of the Vicker's hardness test. Outline the procedure for carrying out the Vicker's hardness test on a steel (ii) sample. (10 marks) Explain each of the following defects caused by hardness test: (c) (i) pincushion indentation; (ii) barreled indentation. (4 marks) 16. (a) (i) Define the term powder metallurgy. State four commercial importance of powder metallurgy technology in the (ii) manufacturing industry. (5 marks) Explain three methods of producing metallic powders for powder metallurgy. (b) (6 marks)

(c)

Describe the conventional steps in the powder metallurgy production process.

3

(9 marks)

Define each of the following terms with reference to iron carbon equilibrium 7. (a) diagram: phase; (i) thermal equilibrium diagram; (ii) (iii) solidus line; (8 marks) tie line. (iv) (4 marks) State four uses of the equilibrium diagram in metallurgy. (b) Sketch and label the iron-carbon thermal equilibrium diagram. (8 marks) (c) Describe composite materials and state two of their advantages over (a) (0) metals. Explain how high strength is achieved in laminar composites. (6 marks) (ii) Outline two functions of each of the constituents of a fibre reinforced polymer matrix (b) (4 marks) composite. State four properties of ceramics. (i) (c) Explain why ceramics are more brittle than metals. (ii) Outline three ways in which toughness in ceramics can be improved. (iii) (10 marks)

THIS IS THE LAST PRINTED PAGE.



4